



TURBINE ENGINE OVERHAUL P&W JT8D & JT8D-200  
 13570 S.W. 129th Street, Miami Florida 33186 \* Ph.: (305) 254-0034 Fax (305) 254-0037  
 FAA Approved Repair Station No. Q6GR293Y

**ENGINE LIFE LIMITED COMPONENT RECORD**

<b>WORK ORDER</b>	<b>ENGINE MODEL</b> JT8D-15	<b>ENGINE S/N</b> 648792	<b>DATE</b> 5-26-09
<b>ENGINE TOTAL TIME</b> 77,859.00	<b>CUSTOMER</b> Commercial Turbine Services		<b>ENGINE TOTAL CYCLE</b> 67,925

**N-1 COMPRESSOR DISKS**

STG	PART No.	SERIAL NO	LIMIT MAX HRS	TOTAL HOURS	REMAIN HOURS	LIMITS MAX CYCLES	TOTAL CYCLES	REMAIN CYCLES
C-1	817401	P24165	30,000.00	22,578.00	N/A	20,000	15,628	4,372
C-2	790832	S55516	30,000.00	18,226.00	11,774	20,000	12,897	7,103
C-3	799773	R95872	30,000.00	17,563.00	12,437	20,000	12,761	7,239
C-4	799504	S07495	30,000.00	17,563.00	12,437	20,000	12,761	7,239
C-5	745705	R89154	30,000.00	17,563.00	12,437	20,000	12,761	7,239
C-6	745706	R86817	30,000.00	17,563.00	12,437	20,000	12,761	7,239

**N-2 COMPRESSOR DISKS**

7TH	5006007-02	BENCAL9069	30,000.00	7,143.00	22,857	20,000	5,857	14,143
8TH	787208	BENCAM0822	30,000.00	7,143.00	22,857	20,000	5,857	14,143
9TH	822109	TBA	30,000.00	0.00	30,000	20,000	0	20,000
10TH	772510	BENCAM2507	30,000.00	7,143.00	22,857	20,000	5,857	14,143
11TH	772511	BENCAM0010	30,000.00	7,143.00	22,857	20,000	5,857	14,143
12TH	798512	BENCAM1774	30,000.00	7,143.00	22,857	20,000	5,857	14,143
13TH	5003613-01	BBDUAN6689	30,000.00	7,143.00	22,857	20,000	5,857	14,143

**TURBINE DISKS**

T-1	5004301-01	P29501	30,000.00	16,607.00	13,393	20,000	12,145	7,855
T-2	803122	B402AA0935	30,000.00	12,421.00	17,579	20,000	9,562	10,438
T-3	795603	T71974	30,000.00	12,421.00	17,579	20,000	9,562	10,438
T-4	789104	B404AA0398	30,000.00	12,421.00	17,579	20,000	9,562	10,438

**DRIVE SHAFTS**

HPT SHAFT			N/A		N/A			0
LPT SHAFT					0.00			0

**COMMENTS:**

( ASB 6431 ) DUE: 08/01/17

TSEHM:	0	Hrs
CSEHM:	0	Cyc
TSHSI:	0	Hrs
CSHSI:	0	Cyc

WARRANTY: 1000 HRS / 12 MONTHS WHICHEVER OCCURS FIRST.

ASKING PRICE:

Prepared by:

Gustavo Codina  
 Dir. of Quality Control

Remarks: All data was provided by the customer.